PHONE: (303) 629-0221
FAX: (303) 623-7830

2617 West Holden Place, Denver, Colorado • 80204

FRONTIER FIRE PROTECTION INC.

FIRE PROTECTION ENGINEERS AND CONTRACTORS

June 3, 2013

Project:

Medical Center of Aurora – Imaging Center Suite 110
1444 South Potomac Street
Aurora, Colorado 80012

Fire Sprinkler Permit No. 2013-647594

The fire sprinkler system scope of work for Suite 110 included relocating 40' of 1-1/4" branch line, adding 23 pendent heads from existing outlets, adding 4 upright heads and adding 4 pendent heads from new copper piping within the MRI room.

Due to the existing system zoned by floor, occupied adjacent areas and the limited amount of modifications performed we feel a hydrostatic test is not necessary. Requiring a hydrostatic test would create an undue burden on the existing tenants as it would be necessary to remove system from service and close adjacent occupied areas for the duration of testing.

Sincerely,

Tracy Skinner
Frontier Fire Protection